## Annexure D

Dated: 19.03.2025

## **BUILDING SAFETY CERTIFICATE**

It is certified that the building or premises) at	NEADOLD	ling VISAK				
VISAKHAPATNAM - 40		ring block(s)/Flo	oor(s) as per o	details below:	•••••	
Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	S R BLOCK R P BLOCK G + 1	VIVEKANANDA BLOCK G + 1	J B BLOCK G+1	S C BOSE BLOCK G+1	A P J BLOCK G + 2	PRAHLADA C S BLOCK
The building is owned/or of the Institution) have Building code Rules, a Department/ Govt.) on.  DR.(SMT).ESHWARI P	complied with and verified b	the Building s by the officers (date of ins	safety require concerned c spection) in t	ments in acco GVMC, VISAI fhe	rdance with Na KHAPATNAM (Na	(name ational
Manager/Secretary or I						cy for

1.

No.

2.

3.

4.

Issued on 19 03 2525 at by

with rule and subject to compliance of the specific conditions as appended.

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Name Engineer

Designation Visakhapatnam

Name & Address of Department Office: TNAM